








x3

M6*40A




X68

M15*11B




X68

M3.5*14C




X16

M5*40D



X51

E




X8

M4*16F




X8

G




X4

M3*12H



X16

J




X38

K




X1

M8*40M




X12

12 inchesL



X4

M3*16N



N1




N2


X6




$$L = CR + DR + CL + DL$$




L




CR



DR



DL



CL

1


C

X12



L

X3




CR

CL

CR

C



C*6

6

CL*3

7

C*6


CR*3



C

CL


C



2

A

X14



E

X4



M

X2



M*1

A*7

6


A*7

7

E*2

E*2


M*1




3

B



X7







4





5





6





7






8






9







10















12






13












17





x3

18





x3

19



x3

20



x3

21

H

X12




L

X3



DR

DL





x3


22

D



X6



23




24



25

B

X6



26


H

X4




L


X1



DR



DL



27

