







x3

M6*40


A



X32

M15*11


B



X32

M3.5*14


C



X14


M5*40

D



X21


E



X6

M6*25


F



X48

M12*11


G



X48


M3*12

H



X16

J



X28


K



X1



12 inches

L




X4


$$L = CR + DR + CL + DL$$




L



CR



DR



DL

CL

1


C

X12






L

X3



CR


CL



2



F

X24






E




X4



3




4



5

G


X12







6

G



X12



7



8








9

G




X6






11

A




X6



12

F





X12

G



X6




13

G



X6




14

A




X2



B




X6



16

B


X2





17

D

X3




18





x3

19





x3

20





x3

21





x3

22




x3



23



24




25



26

B

X6



27


H

X4




L

X1



DR



DL

