














HARDWARE LIST

A X18  M6*40mm	B X18  15*11mm	C X20  3.5*12	D X2 	E X27 	F X5 
G X71  M6*25mm	H X71  12*10mm	J X5 	K X10 	L X2 	M X4 
N X1 	P X2 	Q X22 	S X28  3*12		


STEP 1



STEP 2



STEP 3



CX10



GX20



M6*25mm



FX5



STEP 4






HX14






12*10mm




STEP 5




STEP 6





STEP 7



STEP 8



STEP 9






BX6




15*11mm


STEP 10



E X7



G X4




M6*25mm










H X4





12*10mm





STEP 11




STEP 12




STEP 13




STEP 14




STEP 15




STEP 16




STEP 17






STEP 18





STEP 19







STEP 20










STEP 21



STEP 22



STEP 23



STEP 24

