








M6*40


A



X40

M15*11


B



X40

M3.5*14


C



X18


M5*40

D



X25


E



X6

M6*25


F



X42

M12*11


G



X42


M3*12

H



X18

J




X28

K



X1


M



X1

12 inches


L



X4

M6*40

N



X8


M4*16

P




X10

Q






X5

R



X2

$$L = CR + DR + CL + DL$$



1


C

X12






L

X3



CR


CL



2



F

X24



E

X4



3

C

X2





L

X1




CL



4



F

X6



E

X2




5

G



X12




6





G





X12



7



8




9





G





X6





10





11





12





13





14



15




16



17

G


X2







18

D

X4






B




X6




21



D



X3




22





x3

23





x3

24



x3

25



x3

26

H

X12




L

X3



DR

DL





x3


27

D



X6





28



29



30



31

