




Assembly Instructions/Montážní návod/Instructions de montage/Szerelési útmutató/
Montageanleitung/Instrukcja montażu/Navodila za sestavo/Upute za sastavljanje





M6*40


A



X60

M15*11


B



X60

M3.5*14


C



X32


M5*40

D



X58

E



X1

F



X8


G



X8

M3*12

H



X32


J



X38

12 inches


L



X8

M8*40

M



X2

N



N1




N2

X20

P

M6*35



X14



Q

M6*30




X12


$$L = CR + DR + CL + DL$$




L




CR



DR



DL



CL


1

C

X16




L



CL CR

X4



C*8


6

CL*4

12

C*8


CR*4



2

A

X8




A*4





6

A*4



12




3



4





5




x2



6





7




8



9




10





B





X8






12






13





14







16




17



18

B


X6



19


D



X4



M

X2







21


E



X1




22





x6

23





x6

24



x6

25



x6

26


H

X24




L

X6



DR

DL





x6

27


D

X12





x2

28



x2

29




30

B



X12




31

H




X8

L




DR

X2



DL



x2

