










M6\*40


A



X23

M15\*11


B



X23

M3.5\*14


C



X4

M5\*40


D



X27

M6\*40

E



X22


M4\*16

F



X4


G



X2


M3\*12

H




X4

J



X12


K



X1

12 inches


L



X1

M6\*40


M



X12

M6\*12


N



X4

M6\*30


P



X8

M6\*25


Q




X8

---


$$L = CR + DR + CL + DL$$




L



CR








DR





DL

CL

# 1




# 2




3

A



X6




4

B




X6



5

E


X6



6

D



X6



# 7

M


X6




# 8

N



X4







9





10







# 12





# 13

Q


X8





# 14





# 15








# 16



# 17







20

